## Department of Conservation and Recreation NPDES Storm WaterManagement Program Permit Year 11 Annual Report

## **Table 6 State Forest Facility Best Management Practices**

		BMP #	2-5	2-7	2-8	3-1	3-4	6-13	6-14	6-15	Z 10								
		BMP #	Public Concerns/	ns/ Massachusetts	Lakes and Ponds		Drainage Infrastructure Inventory		CB Repair/ Discharge Pipe Cleaning Needs Assessment		6-18 Maintenance Activity Schedule (MAS)								
			Feedback on DCR Website								Maniciance Activity Sciedus (MAS)								
Facility	Town	Measurable Goal	Forward concerns/ feedback received to appropriate dept. Track response to concerns.		ll Continue to	Locate Outfalls 1.	Develop state-wide drainage infrastructure map.	Perform state wide assessment of roadways and infrastructure conditions annually.		Perform an annual review of roads and parking lots within UA during wet weather conditions to identify ponding or flooding areas.		Clean CB and piping every two years.	CB rehabilitation and repair annually and clean per inspection recmndn.	Inspect detention ponds annually, clea per inspection recmndn.		Inspect drainage swales annually, clean per inspection recmndn.	Inspect water quality inlets 2x/yr clean per inspection recmndn.	Inspect infiltration , systems 2x/yr, clean per inspection recmndn.	n Building maintenance weekly, clean per inspection recmndn.
	ate Lowell, Dracut, Tyngsboro		Met	Met	Met	Met	Met		Met		Met	In Prog	////	77777	/////	////	/////	/////	Met
Forest Shawme-Crowell State Forest	Bourne Sandwich		Met	Met	Met	Met	Met		Met		Met	In Prog		Created Wetland					Met
Permit Year 11 Notes			Concern/ feedback tracking and response system implemented.	k DCR attends monthly and is an active participant.	DCR continues to sponsor this			roadways and drainage infrastructure annually. Drainage infrastructure is assessed during	DCR continued to systematically clean catch basins and water jet the associated outlet drain pipes using private contractors overseen daily by DCR staff. Contractors cleaned and water jetted 3,395 catch basins and manholes with these locations recorded using GPS. For the fiscal year ending in June 2014 DCR spent \$1.27M to clean and repair catch basins.	where ponding causes safety	To insure adequate street	DCR continued to systematically clean catch basins and water jet the associated outlet drain pipes using private contractors overseen daily by DCR staff. Contractors cleaned and water jetted 3,395 catch basins and manholes with these locations recorded using GPS.	Unable to repo specific data be Begun to deve Schedule (MA	ort on detention basin ase is not available. I lop web-based report	s, water quality swa Drainage system infi	rastructure inver	ntory proposed will n	nake this possible.	Met MAS schedule.
Planned Activities - May 20 to April 2015	14		Continue system.	Continue participation.	Continue sponsorship.	Verify the location and condition of outfalls located from paper maps during illicit discharge detection field tasks.	n The infrastructure database is a dynamic work in progress. Updates will be made to the database when new construction takes place. Corrections to the database will be made as areas are visited during the illicit discharge investigation.	Perform state wide assessment of roadways and infrastructure conditions.	DCR will continue to systematically clean catch basins and water jet the associated outlet drain pipes, as determined necessary, using private contractors overseen daily by DCR staff.	parking lots within UA during wet weather	Sweep all streets at least once. Continue to provide and fund contract for sweeping roadways that discharge to impaired receiving waters using mechanical and vacuum sweeping equipment at least fou times per year, and monthly in areas where cars are allowed to park.	jet the associated outlet drain pipes, as determined necessary,		eet Maintenance Acti at to more effectively	•			tructure inventory. 1	Develop web-based

Goal Not Met
Goal in Progress
Goal Achieved
Goal Not Applicable
Goal Metrics Not Available

10/6/2014 Table 6: Page 1 of 1